

Oil Field Environmental Incident Summary

Incident: 20160624133140 **Date/Time of Notice:** 06/24/2016 13:31

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: SSU 22-11H

Field Name: STONEVIEW

Well File #: 28798

Date Incident: 6/20/2016 **Time Incident:** 08:00

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 95

Sec: 11

Qtr: SW NE

Location Description:

Submitted By: Scott Hunsakor

Received By:

Contact Person: Scott Hunsakor
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other - List Under Desc of Cause below

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/12/2017

Clean Up Concluded: 6/23/2016

Risk Evaluation:

none

Areal Extent:

Small skim approx. 250 ft. by 500 ft. in the pasture east of the flare pit

Potential Environmental Impacts:

none

Action Taken or Planned:

Shut well in and repair treater. Talked to landowner and he said to leave oil sheen. We will mow the grass short and rake up the clippings and dispose of.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 6/24/2016 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident report, release impacted area off location. Follow-up is required.

Date: 7/1/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 6/30/2016.

Area sprayed pasture to the north of the flare. Responsible party is going to mow the impacted grass and collect the clippings. I suggested to the company to fence off the impacted grass from the livestock. The landowner, however, contacted me and explained that he didn't want the area fenced off.

More follow-up is necessary to ensure cleanup.

Date: 9/9/2016 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone call with responsible party. Impacted grasses have been mowed and taken to R360/Prairie Disposal. By request of the landowner, area was not scraped.